

<b>NEW HOLLAND</b>					
<b>A/A</b>	<b>ΤΥΠΟΣ</b>	<b>ΙΣΧΥΣ (Hp)</b>	<b>ΑΡ. ΑΠΟΦΑΣΗΣ</b>	<b>ΤΥΠΟΣ ΚΙΝΗΤΗΡΑ</b>	<b>ΑΡ. ΑΠΟΦΑΣΗΣ</b>
<b>1</b>	LM 445 A	96.56	8299/E13/1065/11-5-2004	IVECO F4GE0454C*D6	e3*97/68GA*2001/63*1003*01
<b>2</b>	LM 415 A	96.56	10352/E17/1496/12-5-05 Μ-ΕΓΚ-ΚΤ/02-00	IVECO F4GE0454C*D6	e3*97/68GA*2001/63*1008*01
<b>3</b>	LS 170	52	10931/E17/1640/21-7-05 Μ-ΕΓΚ-ΚΤ/05-00 8270/E17/1177/26-1-07 (Διευκρινιστική)	ISM-N844T	e11*97/68DA*0187*00
<b>4</b>	LS 150	38	10932/E17/1641/21-7-05 Μ-ΕΓΚ-ΚΤ/06-00	ISM-N843H	e11*97/68DA*00/000*0135*01
<b>5</b>	L 150	38.48	Μ-ΕΓΚ-ΚΤ/06-01 12100/E17/3264/1-7-08	ISM-N843H-D-38 SL	e11*97/68KA*2004/26*0135*14
<b>6</b>	L 170	52	14178/E17/4256 Μ-ΕΓΚ-ΚΤ/05-01	ISM-N844T	e11*97/68JA*2004/26*0853*00
<b>7</b>	L 160	47	14178/E17/4256 Μ-ΕΓΚ-ΚΤ/05-01	N844-C-46SL	e11*97/68DA*2001/63*0135*06
<b>8</b>	L 160	46,64	9188/E17/1985/1-9-11 Μ- ΕΓΚ-ΚΤ/05-03 ΑΔΑ: 4ΑΧΑΒ-ΠΒΧ	ISM N844-C-46SL	e11*97/68KA*2004/26*0135*14
<b>9</b>	L 170	52	Μ-ΕΓΚ-ΚΤ/05-02/6-7-11 ΑΔΑ: 4ΑΣΨΒ-ΜΗΩ	ISM N844T	e11*97/68JA*2004/26*0853*01
<b>10</b>	L 150	38,48	Μ-ΕΓΚ-ΚΤ/06-02/6-7-11 ΑΔΑ: 4ΑΣΨΒ-748	ISM N843 H-D-38SL	e11*97/68KA*2004/26*0135*11
<b>11</b>	FR 9060 (Εργοστασιακός τύπος 535) (Διανομέας Εναιρώματος)	544	Μ-ΕΓΚ-ΚΤ/24-00/21-6-2012 ΑΔΑ: Β4Λ3Β-Η6Ε	Iveco ή Iveco Motors F3CE0684F*E	e3*97/68HA*2004/26*1032*02
<b>12</b>	L160	46,6	Μ-ΕΓΚ-ΚΤ/05-04/8-11-2012 ΑΔΑ: Β4ΣΟΒ-ΗΒΝ	ISM N844-D-46SL	e11*97/68KA*2004/26*0135*14
<b>13</b>	L218	60,79	Μ-ΕΓΚ-ΚΤ/25-00/9-10-2012 ΑΔΑ: Β43ΒΒ-ΠΗΖ	ISM N844LT-D-60 (SL57)	e11*97/68JA*2004/26*0886*05









